

# TROUBLESHOOTING AND MILLING STRATEGIES

## Surface finish quality

*If surface finish quality is sub-par or does not meet specifications*

- Review/improve workpiece holding and tool holding
- Reduce feed rate (IPM)
- Increase cutting speed (RPM)
- Review tool selection / switch to tool better suited for finish requirements

## Vibration

*Excessive tool wear, poor surface finish, loud audible tool noise, and poor dimensional accuracy*

- Review/improve workpiece holding and tool holding
- Increase feed rate (IPM)
- Decrease cutting speed (RPM)
- Review milling strategy.
  - ie: Climb vs conventional milling, or WOC / DOC
- Review tool selection.
  - ie: Number of teeth, helix angle, etc.

## Chip congestion / Tool breakage

*Insufficient chip evacuation, chipping on cutting edges, or edge build-up resulting in poor tool life or breakage*

- Review delivery method of coolant / air
- Increase / adjust coolant flow
- Reduce feed rate (IPM)
- Review tool selection.
  - ie: Number of teeth, helix angle, etc.

## Feed rate adjustments for extended DOC

*When extended DOC is used, adjustment of the feed rate may be necessary to avoid deflection, chatter, and poor surface finish*

- if DOC = 1xD, use feed rate per recommended values
- if DOC = 2xD, reduce feed rate 50%
- if DOC = 3xD, reduce feed rate 75%
- Cutting speed (SFM) can remain unchanged up to DOC of 3xD

## Feed rate adjustments for Ramping & Plunging

*Feed rates should be adjusted for ramping and plunging applications*

- On a 90 degree vertical plunge with center cutting endmill reduce feed rate 70%
- Ramping with ramp angles 1-15 degrees, use normal recommended feed rates
- Ramping with angles from 15-30 degrees, reduce feed rate by 30%
- Helical plunging reduce feed rate by 15% with .100-.200 DOC per revolution

## Entry in Hard Material

*Feed rates should be adjusted into material over 44 RC*

- Arcing into the cut is always recommended if possible
- When arc entry is not possible, see recommendation for feed reduction below:
  - When WOC is 1xD, reduce feed 50% until tool is engaged
  - When WOC is .5xD, reduce feed 30% until tool is engaged
  - When WOC is .25xD, reduce feed 20% until tool is engaged

## CONVERSIONS

### Inch

|     |                         |                                    |
|-----|-------------------------|------------------------------------|
| SFM | Surface Feet per Minute | $SFM = RPM \times D / 3.82$        |
| RPM | Revolutions Per Minute  | $RPM = 3.82 \times SFM / DIA$      |
| IPT | Inches Per Tooth        | $IPT = IPM / (Z \times RPM)$       |
| IPM | Inches Per Minute       | $IPM = IPT \times Z \times RPM$    |
| CIM | Cubic Inches per Minute | $CIM = Feed \times WOC \times DOC$ |

D = Tool Diameter    Z = Number of flutes  
WOC = Width Of Cut    DOC = Depth Of Cut

### Metric

|    |                           |                                        |
|----|---------------------------|----------------------------------------|
| Vc | Surface Meters per minute | $Vc = 3.1416 \times D \times n / 1000$ |
| n  | Revolutions per minute    | $n = Vc \times 1000 / 3.1416 \times D$ |
| fz | Feed per tooth            | $fz = vf / n \times z$                 |
| Vf | Millimeters per minute    | $vf = (n) \times (z) \times (fz)$      |

D = Tool Diameter (mm)    Z = Number of flutes

### Conversion Formulas

|            |                    |
|------------|--------------------|
| Inch to mm | Inch number x 25.4 |
| mm to Inch | mm number x .03937 |

## PROFILE THUMBNAILS:

